## MARION COUNTY SURVEYOR'S OFFICE

## SECTION CORNER RECORD

DEBRA S. JENKINS MARION COUNTY SURVEYOR

SEC. 22 TWN.  $14_{\text{N}}$  RNG.  $2_{\text{E}}$ 

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

Date: 5-7-10

Party Chief: Greene / Wilcoxen


Crew: Taylor

Type of Marker: Harrison


Method of Establishment: County: 5-18-1999

IN S.P.C. E Zone, NAD 83 (1986)

Name: 14022201 N: 488 540.437 8(m) E: 45 001.702 6(m)



Mooresville Rd 8000 S



Corner originally set as a post in 1820 by Wm. B. Laughlin with the following witnesses: 12" Ash bearing S 12 W 23 links and a 14" Beech bearing S 19 W 25 links (Marion County Atlas p. 3). A survey by Frank Unversaw on 12/17/1958 indicates a stone set (Decatur Legal Book p. 54). Corner referenced by Monroe on 4/14/61 and called a stone set. Corner referenced by Bookedis on 8/24/67 and called a stone. Corner referenced by Hylden on 10/25/74 and called a RR spike. Corner was excavated by Greene on 7/11/89 and a RR spike was found 3" down. A 1" guide pipe was found 6" down beside a stone 16" down. A #205 cast iron Harrison monument was set in position of the stone. Wilcoxen on 12/21/94 called a Harrison. Kiste on 5/18/1999 called a broken Harrison. Corner was reset by Wilcoxen on 10/01/2001 per resurfacing project. Kiste on 5/12/05 called a Harrison. Corner excavated on 5/7/10 by Wilcoxen per resurfacing project and a 3" riser was put on existing monument.

REF	DISTANCE	DESCRIPTION
1.	30.64'	Mag nail w/brass washer SE PwP #8-771YA 12" up
2.	50.60'	Top nut of fire hydrant
3.	90.25'	Mag nail w/brass washer W PwP # 350-771YB 12" up